

Commencing at the Northwest corner of section 14 Tp. 4 S. R.26 E.W.M. thence S 89° 54'E
 3.3 chains, thence S 51° 33'E 8.3 chains, thence S 32° 15' W 12.7 chains, thence
 S 8° 54'E 16.9 chains, thence S 19° 49' W 3.4 chains, thence S 32° 43' W 5.9 chains
 chains to place of beginning.
 thence North 40

Commencing at the $\frac{1}{4}$ corner between sections 14 and 15 Tp. 4 S.R.26 E.W.M. thence
 S 13° 05'W 10.6 chains, thence S 23° 51'W 7.6 chains, thence S 24° 57'W 10.6 chains
 thence S 42° 54'W 6.0 chains, thence S 20° 39'W 15.1 chains, thence S 19° 52'E 6.0 chains
 thence S 7° 20'W 2.1 chains, thence S 71° 42'W 15.1 chains, thence S 8° 10'W 5.1 chains
 thence S 48° 48'W 7.6 chains, thence S 44° 57'W 2.0 chains, thence S 6° 53'W 7.7 chains
 thence S 9° 43'W 9.1 chains, thence S 16° 59'E 6.3 chains, thence S 89° 54'W 7.7 chains
 thence North 100.0 chains, thence N 89° 54'E 40.0 chains to place of beginning.

Loy M. Turner Co. Surveyor.

May 30-31 1913

5/30-31

Folder 1203, Date 1913

Book: 2, Page: 21A