



**SECTION 14, TAN, R221E, WM.**  
Scale: 1"=600'

10/11  
15/14  
Ind. 1" pipe w/washer  
(Corp of Engineers)

11/12  
14/13  
Coordinates translated for this survey  
This corner presently inundated by Lake Umatilla

Note:  
Section corner 11/12 was re-established from the following Oregon State Highway Data for the Relocated line Weaner Junction Boardman Section Columbia River Highway August 1960 - Revised June 1982 4/1/83

**DETAIL "C"**  
n/s

11/12  
14/13  
Coordinates translated for this survey

16/15  
21/22  
Ind. 1" pipe w/washer  
(Corp of Engineers)

Ind. 2" pipe

Ind. 8" pipe

**DETAIL "A"**  
Reproduction of corner 15/14  
n/s

16/15  
21/22  
Ind. 1" pipe w/washer  
(Corp of Engineers)

**DETAIL "B"**  
n/s

Notes:  
1. Section corner 15/14 established by LeLand Ascher (L.S. 635), Hayes and Harris and no. 63-1604 found to be substantially in error - see Detail "B"  
2. Bearings are based on Ascher's bearing from 15/14 to 21/22. Section corner 21/22 was also found Ascher's location of 21/22 was found to agree with his location of 37/36 and 43/42.

Note:  
( ) - denote Ascher's bearings and distances.

REGISTERED PROFESSIONAL LAND SURVEYOR

CLAYTON D. HARRIS

<b>KRUMBEIN ENGINEERING CO.</b> ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon	SCALE AS SHOWN
	DATE 10/12/1978
Survey for <b>LOUIS LE TRACE</b> Section 14, TAN, R221E, WM.	OWN BY P.L.S.
	CKD BY J.H.B.
	SPRNG. NO. 478-1/C