

Folder 1132, Date 4-1914

Book: 1, Page: 26D-27A

Commencing at the Section corner to Secs, 10-11-14-15 Tp. 5 S R 26 E.W.M. , thence S 89° 39' W on true line as per field notes between Secs. 10-15 40 chains found no trace of original corner after diligent search and proceeded to re-establish a corner by placing a stone 12x9x5 marked $\frac{1}{4}$ CS on East face in mound of earth with ^{pits} as per instructions, thence S 89° 39' W. 20 chains, set stone 20x12x10 for (40) corner, thence North 80 chains, built stone mound on section line between Secs 3-10 for (40) corner thence N 89° 42' W on true line as per field notes, between Secs. 3-10 20 chains, found no trace of original stone as described in field notes. The point was on a steep side hill covered with rocks and in all probability the stone had been displaced by stock as it is in the immediate vicinity of a sheep corral. Not finding any trace of the original corner I proceeded to re-establish the corner. Set a stone 20x3x5 marked with 5 notches on the South and 3 notches on the East also CS on the South with mound of earth and pits as per instructions.

1132, Date 4-1914

1, Page: 260-274

ions for corner to Secs. 3-4-9-10 Tp. 5 S R 26 E.W.M.

April 6 1914

Loy M. Turner Co Surveyor.

Corner of the 1/4 corner between Secs. 1 and 6 Tp. 5 S. R. 25 and 26 E.W.M.