

CORNER RESTORATION FORM

Township 1 SOUTH Range 24 EAST Section 4 County MORROW

State OREGON Date 02/07/03 Number D-11

Corner Designation : CS1/16 CORNER SEC. 4

- Condition Report Only
- Not Found
- Renewed
- Surveyed In
- Referenced


Previous Renewals _____

Monument (s) Found: (Condition and Source)
ORIGINAL CORNER WAS ESTABLISHED BY D.P. THOMPSON IN
1865 UNDER CONTRACT No. 109, WHICH WAS A STANDARD
LOCATION BY SURVEY, NO MONUMENT WAS SET.

MONUMENT DETAIL

Found Set

Accessories Found:
NONE



SET 5/8"Ø X 30" REBAR WITH YELLOW PLASTIC CAP.

Monument & Accessories Set (Procedure and Description)

- SET 5/8" X 30" REBAR AND CAP 0.30' ABOVE GROUND BY SURVEY.
- SET PK NAIL IN FENCE POST 8.66 FEET EAST OF CORNER.
- SET PK NAIL IN FENCE POST 10.27 FEET SOUTH OF CORNER.
- SET STEEL FENCE POST 3 INCHES SOUTH OF CORNER.

Sketch of Monument, Accessories and General Area

REGISTERED PROFESSIONAL LAND SURVEYOR

Danny K. Cummings

OREGON
JAN. 21, 1988
DANNY K. CUMMINGS
2316

RENEWS: 12/31/2015

Agency: CK3, LLC
 368 SW 5TH AVE
 ONTARIO, OR

Party Chief DAN CUMMINGS

Notekeeper L. KING

Witness(s) LANCE KING

Field Book 0-199

Client MONTY CRUM

Job # S0-02020

COUNTY SURVEYOR RECORDING INFO

Received 4-14-2014

Filed S.K.H.

Survey No. 2014-1699C

Index No. D-11