



714

# OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT

## MORROW COUNTY SURVEYOR'S OFFICE

<b>SECTION</b> 27	<b>TOWNSHIP</b> 4 S.	<b>RANGE</b> 25 E.	
<b>MORROW COUNTY</b>		<b>DATE</b> June, 2012	
<b>CORNER DESIGNATION:</b>			
(Please check one)			
<input type="checkbox"/> <i>Condition Report Only</i> <input type="checkbox"/> <i>Not Found</i> <input type="checkbox"/> <i>Renewed</i> <input type="checkbox"/> <i>Unrecorded</i> <input checked="" type="checkbox"/> <i>Surveyed In</i> <input type="checkbox"/> <i>Referenced Out</i>			
4S25T14			
<i>Previous Renewals / Surveys. etc.</i> None.			
<i>Monument(s) &amp; Accessories Found: (Condition &amp; Source)</i> NA			
<i>Monument Detail:</i>	<i>Sketch:</i>		
			
<i>Monument Set (Procedures and Description):</i> Set 5/8"x30" Iron Rod with a 3-1/4" Aluminum Cap stamped as shown above, 20" in the ground and raised a mound of stone around it.			
<i>New Accessories:</i> Set two 5/8"x20" iron rods with 2" Aluminum Caps stamped Oregon Dept. of Transportation. The monument and references were ties using Leica System 1200 RTK GPS. Bearings and distances to corner as follows: RP1 - S3-18'W, 12.90 Feet, RP2 - N88-55'W, 9.71 Feet			
<i>Location &amp; Comments:</i>		<i>Compass Declination:</i>	
<i>Firm / Agency</i> Oregon Department of Transportation, Geomtronics Unit			
<i>Party Chief</i> J. David Brinton, PLS			
<i>Notes</i>			
<i>Witness</i> Bill Dye, PLS			

SURVEYOR'S SEAL

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*J. David Brinton*

OREGON  
December 2, 1983  
J. David Brinton  
2065

RENEWAL DATE: 12/31/13