

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-17

History of original corner establishment:

Corner originally established in 1884, by Frank W. Campbell, under General Land Office contract No. 507. Surveyor General's Notes State: (See those notes for details)

DIAGRAM
TAS R28E
S221S23

S271S26
T28E

In 1982 the Bureau of Land Management re-monumented this corner, from existing original evidence. (See those notes for details)

Description of corner evidence found:


Found a 3-1/2" brass cap monument, stamped as shown on the DIAGRAM.

Found bearing trees of record as described by the original and BLM notes.

Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained corner by setting a steel post with warning sign South 1 ft. from the corner.

Maintained Bearing trees by nailing Bearing Tree Signs and Warning signs to trees, where needed, and painting a 6" red band around all trees.



Work by D.M. Ferguson, PLS 848, Mt. Vernon Ore.
On Aug. 15, 1984
Witnessed by J. David Brinton, PLS 2065

Office of..... SURVEYOR..... County of WASCO
State of Oregon..... I hereby certify that the within instrument was filed in this office for record on the 10th day of September, 1985
David H. Kambain..... by Brinton..... Brinton
(COUNTY OFFICIAL) (DEPUTY)

RECEIVED BY
Morrow County Surveyor

Date 1-10-86
Filed by MLD
No. 001-K