CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index: M-13

History of original corner establishment:

South 1/16 corner secs. 15 & 16, T.5S., R28E., W.M.

Original survey of township by Sanderson in 1881.
Township retraced by Carter of GLO in 1938.
Corner not set in these surveys.

DIAGRAM

T5S R28E
S1/16
S16 1 S15
1979
PLS 1638

Corner set in 1979 by PLS 1638. His record reads:
I set the monument described below at the midpoint
between found SE corner and W 1/4 of Section 15.
At the position described above, I set a 2 1/2" x 30"
iron pipe 18" in the ground, with a brass cap marked:
(see diagram)
From which I scribed BT's:
A fir 12" in diam. bears N 33°E 18.00' marked S1/16 S15 T5S R28E BT.
A fir 11" in diam. bears N 86°W 30.9' marked S1/16 S15 T5S R28E BT.

Description of corner evidence found:
Found the iron pipe with brass cap stamped as shown in the
diagram. From which:
A 12" dbh Engleman Spruce bears N31°55'E, 17.9' with scribe.

Description of monument and accessories I established to perpetuate the
original location of this corner:
The bearings were based on the surveyed bearing between the NE corner
and the East 1/4 corner of section 16 as recorded in by PLS 1638 in
Morrow County survey 269-K. I set the following new witness tree:
A 8" dbh Lodgepole Pine bears S65°27'E, 6.7' scribed S1/16 S15 BT:
An aluminum washer stamped RLS 852 is nailed between the letters B and T
on the new tree. All the BT's have LSM and BT signs attached.
Painted 6" red bands around all the trees and painted the
scribe blazes red.

This work was done September 22, 1992.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

Office of _____ County of _____
State of _____, I hereby certify that the within instrument was filed
in this office for record on the _____ day of _____, 19____.

_____ by _____
(COUNTY OFFICIAL) (DEPUTY)

Form RS-7100-57 (9/71)

RECEIVED BY
Morrow County Surveyor
Date 11/23
Rec'd By DE
No. _____