


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-9

History of original corner establishment:

Corner originally established 1882 under Contract Survey No. 417, dated 1881.

Corner re-established by Dependent Resurvey authorized 1938 and approved Feb. 21, 1941.



Description of corner evidence found:

1 inch iron pipe with 2 1/2 inch brass cap marked as shown above, from which---

14" L.P. Pine, alive and standing, bears S 82° E (Record S 86° E), 17.8' (record), scribing 1/4 S21 BT legible. Tree has USFS sign 54-3 dated 1946.

14" Spruce, alive and standing, bears S 23° W (Record S 22° W), 29.0' (record), blaze healed, scar visible. Tree has USFS sign 54-3 dated 1972.

Description of monument and accessories | established to perpetuate the original location of this corner:

Attached USFS sign, 54-4 to all trees, painted blaze and a 6" wide band of fluorescent red around trunks.

Set a 6' steel fence post 5' North of corner and attached USFS sign 54-4.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Thomas F. Upton*

OREGON  
FEBRUARY 1, 1975  
THOMAS F. UPTON  
10224

Thomas F. Upton, Certificate No. R.L.S. 1024

Office of Car. Swartz County of Morrow  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 12<sup>th</sup> day of January, 1982  
Darold K. Krumpholtz by Maathia R. Blechman  
 (COUNTY OFFICIAL) (DEPUTY)

FORM R6-7100-57 (9/71)

RECEIVED BY  
 Morrow County Surveyor  
 ☆ GPO-198-276

Date January 12, 1982

Rec'd By M. Swisher

No. 474-K

Ref. diwg nce 40-1K