

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

L-23

DIAGRAM

T6S R29E
O 1/4 S13

History of original corner establishment:

None

Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

T6S R29E
O 1/4 S13
1979
P.L.S 346

Set 3 2/4" x 2" flanged iron pipe with brass cap marked:
from which
Ponderosa Pine, 8" Dia., BRS. W55 3/4" E., 42.3 Ft. Dist.
Marked: O 1/4 S13 BT
Ponderosa Pine, 8" Dia., BRS. W62 1/4" W., 35.2 Ft. Dist.
Marked: O 1/4 S13 BT
6' Iron Fence Post with "Survey Monument" sign within 5' of corner.
6' Iron Tence Post with "Survey Monument" sign within 5' of corner.
All 3" P. have BT tag and painted red stripe. New DPs have brass washer stamped:
P.L.S 346; nailed to lower blade.

Office of County Surveyor County of Oregon
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the day of
(COUNTY OFFICIAL) by (DEPUTY)

REGISTERED
PROFESSIONAL

RECEIVED BY
MORRISON
County Sur