



Bearings are based on a survey for Merle Carlson dated 10-3-77, Morrow County No. 111-K.

- denotes 5/8" i. pin w/ alum. cap set
- denotes monument fnd as noted
- denotes Brass Cap fnd

David H. Krumbein

REVISION BY
Morrow County Surveyors
DATE 12-6-80
DRAWN BY MLD
B-424-K-205

KRUMBEIN ENGINEERING CO. ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon	SCALE 1" = 300'
	DATE 11-6-80
Survey for BOB BERGDAHL Section 14, T4N, R25E, W.M.	DRN. BY M.L.J.
	CKD. BY D.H.K.
	DRNG. NO. 80-186

Job No. 80-171