



SW 1/4, SW 1/4  
Section 25  
Block W18

**NOTE**

Bearings are based on a survey for Morrow County by Krumbain Engineering, Ltd. dated May 8, 1980, Morrow County Survey Records drawing no. D-303-K.  
See Morrow County Survey Records drawing no. D-303-K for West line of Section 24.

- denotes Brass Cap found
- denotes Brass Screw and Washer found
- denotes monument found as noted
- denotes original section breakdown
- denotes line Krumbain Engineering, Ltd. surveyed
- ( ) denotes bearing and distance of record

RECEIVED BY  
Morrow County Surveyor  
Date July 23, 1981  
Rec'd By M. Hughes  
No. C-426-K

*Dani H. Krumbain*

**KRUMBEIN ENGINEERING CO.**  
ENGINEERS - SURVEYORS - PLANNERS  
221 S. Main, Pendleton, Oregon

Survey for  
**MORROW COUNTY**  
24 & 25, T5N, R26E, W18

SCALE	1" = 300'
DATE	JUNE 30, 1981
DRAWN BY	NAI
CHKD BY	D.H.K.
DRNG. NO.	

C-426-K-436