



**NARRATIVE:**

The purpose of this survey is to stake the corners of Bradley's parcel so a fence can be rebuilt. In 1983 Krumbein retraced Tamblin's survey of the Subdivision of Part of Section 24 finding many original concrete monuments and setting rebar at all block corners, Co. #D-622-K. Krumbein's survey matched Tamblin's very nearly. This survey is based on Krumbein's 1983 survey.

**LEGEND:**

- Found monuments, as noted.
- Set 1/2" x 24" rebar with plastic cap #951.
- [000] of Record. Tamblin's 1935 Plat of Subdivision of Part of Section 24.
- (000) of Record. Krumbein's 1983 Survey for Morrow County, #D-622-K.
- E(000) of Record. My 1989 Survey for Morrow County Road Dept. #B-892-E

RECEIVED BY  
 Morrow County Surveyor  
 Date 3/93  
 Rec'd By DE  
 No. B-944-E 716

Detail: N.T.S.

Survey for **WAYNE BRADLEY**  
 In Blk. 12W, In SW 1/4 Section 24, T5N, R26E, W.M.,  
 Morrow County, Oregon  
 2/19/93 Job #59302007  
 Edwards Surveying P.O. Box 763  
 567-3336 Hermiston, Oregon 97838