

SURVEY OF THE TIDE LANDS ON THE COLUMBIA RIVER

SITUATE IN SECTION 19 T. 5 N. R. 27 E.W.M.

Commencing at the south west corner of sec. 19 thence N.39.32ch. to meander cor. between 19 &24 var. $21^{\circ}30'$ E. thence E. on random line 80ch. to meander cor. between sec. 19 & 20 thence south on random line to south east corner of section 19. North on true line 40ch. meander cor between sections 19 & 20 thence N. 13ch. to water in the Columbia river var. $21^{\circ}30'$ E. thence S. 87° course west 29.15ch. thence S. $82^{\circ}30'$ 15.25ch. thence S. $81^{\circ}30'$ 14.39ch. thence S. 69° E. 22ch. to meander corner between sec.

19 & 24

State of Oregon

County of Morrow SS

I hereby certify that the fore going field notes are true and correct

V.H. Heath

Surveyor of Morrow County.

Feb. 3rd.-08.

Folder 1171, Date 2/03/1908
Book: 2, Page: 5B